

SERVICE BULLETIN

Subject: Bowler Console Keypad Failures

Distribution: All customers that have QWERTY keypads installed (shown below)



Issue: Static electricity can cause the internal PCB to fail

Resolution: A new grounding wire can be added to your existing keypad

Description: When the bowlers are using the keypad, it's possible the static electricity generated by the touch of a finger to the keypad can cause failures.

Instructions:

Please see the attached diagram for installing a new ground wire to your existing QWERTY keypads

Thank you...
Steltronic Service Department

